

Menu

HISTORY FILE MAP for year 2008

REALTIME


PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

028:02:09-02:30 21m of 128bps data lost due to DSS-54 being unable to maintain TM lock as a result of antenna mask and low elevation. No DR.

023:20:27-21:02 35m 128bps data lost due to DSS-54 being unable to maintain TM lock as a result of antenna mask and low elevation. No DR.



022:08:24-08:58 34m of 128bps data lost due to late acquisition by DSS-63 (TX problem) while it was attempting to acquire earlier than the scheduled BOT to reduce the gap in coverage. No DR.

027:20:02-21:02 30m of bad 128bps plus 30m of 128bps data lost due to DSS-54 being unable to maintain TM lock as a result of antenna mask and low elevation. No DR.